
All-Digital Baseband 65nm PLL/FPLL Clock Multiplier using 10-cell Library




 $Robert\ L.\ Shuler,\ Jr.^1,\ Qiong\ Wu^2,\ Rui\ Liu^3,\ Li\ Chen^4\ and\ Sridhar\ Madala^5\\ {}^{1}\!robert@mc1soft.com-robert.l.shuler@nasa.gov,\ NASA\ Johnson\ Space\ Center\ EV5,\ 2101\ NASA\ Parkway,\ Houston,\ TX\ 77058,\ USA$ ²qiong.wu@usask.ca, ³rul070@mail.usask.ca, ⁴lic900@campus.usask.ca, Dept. of ECE, Univ. of Saskatchewan, 57 Campus Drive, Saskatoon, SK, S7N 5A9, Canada ⁵sridhar@indusinstruments.com, Indus Instruments, 721 Tristar Dr., Webster, TX 77598, USA

ABSTRACT:

- A compact portable digital library is described which can be easily ported to new processes, and can be customized to provide Radiation Hardened by Design (RHBD) and ultra low power operation.
- The library is used to construct an all-digital clock multiplier to provide high speed clocks, avoiding issues with making analog PLL loops fault tolerant and re-convergent after Single Event Transients



COMPOSITE GATE EXAMPLES:




TINV tri-state cell more efficient for busses

IMPLEMENTATIONS:


- TSMC 65 nm for TMR ADFPLL (current project, this poster)
- XFAB 0.35 μ extensive use for low power / low voltage (1.8v) RF powered implants
- TSMC 90 nm for general radiation testing and analog PLL (Shuler, SEESYM 2010)
- TSMC 0.35 µ early version radiation testing, comparison of flip flops (Shuler, NSREC 2006, IEEE TNS)
- 10 CELLS PORTS TO NEW PROCESS customizable for guard rails, low voltage, includes RHBD

10-CELL LIBRARY cont'd – XFAB layout with Guard Bars, XOR, ½ DICE, Schmidt Trigger:




WHY AN ALL DIGITAL CLOCK MULTIPLIER?

- Clocks need to be ultra-reliable ... other fault management depends on clocks
- Chips need higher speed clocks than can be brought from off chip
- Analog PLLs have difficulties managing SET/SEU, see illustration
- Existing "digital" PLL techniques are sampled data systems, not usable for highest rate clock
- New technologies may not provide analog components and may not even be CMOS



Conventional fault tolerant PLL:

- Errors removed by voters will not correct state in charge pumps or loop filters or fractional dividers
- Accumulation of invalid states may lead to susceptibility to future errors




Best practices from recent literature:

- VCO and logic vote & correct errors within themselves
- Single string in rest of PLL prevents masking problem
- Natural (slow) PLL action corrects other errors eventually
- · Errors reduced but significant vulnerability remains

DIGITAL PLL / FLL / FPLL CONSIDERATIONS


- Magnitude of phase error quantized at 360° or at best 180° degrees, not continuous!
- NCO quantized frequency + quantized feedback signal ⇒ infinite small signal gain ⇒ instability
- Digital (ring) oscillator provides poor frequency resolution (2 gate delays period variance)
- Frequency loops are very stable & phase not needed/meaningful for fractional or high multipliers ...solutions:
- NCO is tapped delay line with 4-phase output using delays, giving ½ gate period increment
- On-chip control provides a frequency loop + a phase loop activated when frequency is close
- Phase loop controls phase only & for one cycle, not accumulating via frequency change

128 stage NCO with 4-phase output (9 bit resolution) 74-360 MHz



ADFPLL ON-CHIP CONTROLLER

- TMR configuration (only one string shown below)
- 9 bit up/down counter for external frequency adjustment
- Very limited I/O pin availability (10) required re-use, external adjustment requires stopping NCO
- Internal multiples of 2x, 3x, 4x & 8x ... compares edges at ever other external clock edge
- Separate frequency and phase detector (very similar, see figure)
- Coarse phase adjustment of 2 gate delays, 3 choices => poor performance at high multiples / freq.
 - Phase adjustment occurs only when frequency matches within one cycle
 - · Repeats several times for high multiples
- Experimental circuit does not prevent harmonic lock (not hard to fix)
 - Simulation is very time consuming (overnight for close start frequency)
 - Need another iteration with finer phase control, no harmonic lock, more test & configuration I/O



TEST RESULTS

- 3 out of 4 NCO's monotonic -4th still convergent
 - Simulations actually performed with 130nm model file due to tools issues
 - Probably could support 8 phase selection with careful simulation
- On 2 of 5 chips the on-chip loop control scanned without any sign of lock
- Very sensitive to over voltage, latchup requiring power cycle
 - 2.5<->1.0v level shifters designed by a grad student ... exceeded bandwidth expectations but poor isolation
 - Guard bars were not used in 1.0v logic under apparently mistaken impression no latchup issue at 1.0v
- Error checking by comparison to ref 100 MHz clock for 2x50, 4x25, and 8x12.5 combinations
 - Several of these, particularly 2x50, very reliable & would run days without error
 - Attempted to obtain time on USAS test at TAMU, but cyclotron problems used up spare time
 - Need more test leads and additional circuits to compare single string & benchmark SEU/SET tests of logic



Test rig: GENESYS Virtex 5, 2v I/O, 1v core supply (a rig w/lab power supply did not work well)

Most waveform distortion due to scope lead coupling

ACKNOWLEDGEMENTS:

- USAS for sharing 65nm chip & making the test board and I/O level shifters
- INDUS INSTRUMENTS for extensive testing of 10-cell library in XFAB .35u
- NASA/JSC for making my time available

